Notes:
1. Yellow shaded results indicate the value exceeds the Residential Soil RSL of 0.3 mg/kg and the Ecological SL of 0.4 mg/kg, but is below Commercial/Industrial Soil RSL of 6.3 mg/kg.
2. Red shaded results indicate values that exceed the Commercial/Industrial Soil RSL of 6.3 mg/kg.
3. When screening against the Residential Soil RSL and Ecological SL, there are widespread hexavalent chromium exceedances with both the START data and the phase 1 RI data. The Phase 2 background study will help to determine if this condition is naturally occurring, or if it is site-related.

N

2		mg/kg	MW-2-0.0-0.5
0.45	J	mg/kg	MW-2-0.5-2.0
	U	mg/kg	MW-2-14.0-16.0

[illegible]		mg/kg	MW-1-0.0-0.5
[illegible]		mg/kg	MW-1-0.5-2.0
4		mg/kg	MW-1-6.0-8.0

2.2		mg/kg	MW-3-0.0-0.5
0.48	J	mg/kg	MW-3-0.5-2.0
	U	mg/kg	MW-3-9.0-11.0

Stream
Nearest Residence
Sumps
MW-2
MW-1
Electroplating Facility
WasteCon
Office
Waste Storage Shed
Bonnie View Road
Former Waste Water Treatment Building
MW-3
Small Pond

Legend

- Monitoring Well Location (to be installed as part of the Phase 1 RI Field Activities.)
- Existing Onsite Water Well Location
- Stream
- Freshwater Forested/Shrub Wetland
- Approximate Site Boundary

0 50 100
Feet

Lane Plating Works, Inc. Superfund Site
Dallas, Dallas County, Texas

Imagery Source: Texas Orthoimagery Program 2015 0.5 Meter DOQQ, Texas Strategic Mapping Program, 20

Hexavalent chromium detections in soil samples collected from Phase 1 RI monitoring well locations.

2019-03-06 M:\Federal\EPA\PAC II\0169-Lane RI-FS_309\GIS\MXDs\SAP\A1_Sap_LP_GW.mxd EA:Dallas jschwartz